

별첨. 석면 비산측정 사진(과천시 별양동 1-15, 그레이스 호텔)


- 측정일자 : 2021. 05. 24.




① 측정 지점 : 부지경계-1



② 측정 지점 : 부지경계-2



③ 측정 지점 : 부지경계-3




④ 측정 지점 : 부지경계-4




⑤ 측정 지점 : 작업장 주변 외부



⑥ 측정 지점 : 위생설비 입구



⑦ 측정 지점 : 음압기 후단-1



⑧ 측정 지점 : 음압기 후단-2



㉨ 측정 지점 : 폐기물 보관지점